



Fox products utilized to restore structural integrity to Trigen steam vaults



Severely deteriorated concrete ceilings and walls in steam vaults located beneath busy city streets.



FX-408 Epoxy Zinc Rich Primer, FX-792 LP Bonding Agent, FX-228 Non-Shrink Grout, and FX-253 Reinforced Polymer Mortar are used to resurface ceiling and walls of vaults.



Close up view of technician applying FX-253 Mortar to wall surface.



FX-792 LP Epoxy Bonding Agent is applied to ceiling prior to placement of FX-253. All exposed Reinforcing is coated with FX-408 Primer.

(OVER)



FX-253 is ideal for overhead and vertical patching.



After all patching work has been completed FX-460 Breathable Coating is applied to walls and ceiling of vaults.



Close up view of completed wall section.



Close up view of completed ceiling section.